

Oil Field Environmental Incident Summary

Incident: 20151230094154 **Date/Time of Notice:** 12/30/2015 09:41

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC

Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: SC-ELLINGSBERG- 154-98-3229H-4

Field Name: TRUAX

Well File #: 29348

Date Incident: 12/29/2015 **Time Incident:** 09:56

Facility ID Number:

County: WILLIAMS

Twp: 154

Rng: 98

Sec: 32

Qtr:

Location Description:

Submitted By: Alex Beach

Received By:

Contact Person: Troy Brunsell
3015 16th Street SW, Suite 20
HOUSTON, TX 77010

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 0.4 Mile

Distance Nearest Water Well: 0.4 Mile

Type of Incident: Other

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	30	Gallons				

Description of Other Released Contaminant:

Transmission Fluid from a semi-truck

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

There is no immediate risk to report at this time.

Areal Extent:

0.25 miles on the county road (west on 48th St NW from lease road).

Potential Environmental Impacts:

There are no potential environmental impacts to report at this time.

Action Taken or Planned:

Braun trucking will be arranging the cleanup of the affected area and disposing it to an approved waste facility.

Wastes Disposal Location: The impacted material will be cleaned up and disposed of at an approved waste disposal facility.

Agencies Involved:**Updates**

Date: 12/30/2015 **Status:** Inspection

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

12/30/2015 at 11:40, on location. Met with site personnel and was shown where incident occurred. Third party trucking firm had a PTO component break and leaked transmission fluid along the lease road and part of the county road. Trucking firm had cleanup company that was already doing work on the wellpad clean up the leak as well. No visible staining on the lease road or county road. No further followup required.

Date: 12/30/2015 **Status:** Reviewed - Follow-up Required

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release impacted roadway. Followup is required.